


## F1040



### GUIDA PER INSERIMENTO PROFILO

#### PIPING ATTACHMENT

Lavoro Finito (finished work)



*Per macchine taglia-cuci*  
*For overlock machines*



Consultare pag. 89 per la panoramica degli attacchi da utilizzare.  
Pls. see pag. 89 for all brackets to be used


Codice	(A)	(B)	(S)	Codice	(A)	(B)	(S)
F1040/15M	15	7,5	M	F1040/40H	40	20	H
F1040/16M	16	8	M	F1040/45M	45	22,5	M
F1040/19M	19	9,5	M	F1040/45H	45	22,5	H
F1040/19H	19	9,5	H	F1040/50M	50	25	M
F1040/20M	20	10	M	F1040/50H	50	25	H
F1040/20H	20	10	H	F1040/55M	55	27,5	M
F1040/22M	22	11	M	F1040/55H	55	27,5	H
F1040/22H	22	11	H	F1040/60M	60	30	M
F1040/25M	25	12,5	M	F1040/60H	60	30	H
F1040/25H	25	12,5	H	F1040/70M	70	35	M
F1040/30M	30	15	M	F1040/70H	70	35	H
F1040/30H	30	15	H	F1040/80M	80	40	M
F1040/35M	35	17,5	M	F1040/90M	90	45	M
F1040/35H	35	17,5	H				
F1040/40M	40	20	M				

## F1035



### GUIDA PER PROFILO CON INSERIMENTO CORDONETTO

#### CORD EDGE PIPING ATTACHMENT

Lavoro Finito (finished work)



*Per macchine taglia-cuci*  
*For overlock machines*



Consultare pag. 89 per la panoramica degli attacchi da utilizzare.  
Pls. see pag. 89 for all brackets to be used

Codice	Entrata (A) (tape size) (mm) (inch)	Lav. finito (B) (finished size) (mm) (inch)	Spessore (S) (thickness)
F1035/19M	19 3/4	9,5 3/8	M
F1035/22M	22 7/8	11 7/16	M
F1035/25M	25 1	12,5 1/2	M
F1035/30M	30 1-3/16	15 19/32	M
F1035/35M	35 1-3/8	17,5 11/16	M

NOTA: USARE CORDINI DI Ø 2 - 2,5 mm

NOTE: USE CORD Ø 2 - 2,5 mm