



## F1050

### GUIDA PER INSERIMENTO PROFILO

*Per macchine piane*  
*For flat bed machines*

Lavoro Finito (finished work)




**PIEDINO CONSIGLIATO**  
*SUGGESTED FOOT*



**G2360A** - per tutte le misure  
*(for all sizes)*

PIPING ATTACHMENT





Codice	(A)	(B)	(S)	Codice	(A)	(B)	(S)
F1050/14M	14	7	M	F1050/40M	40	20	M
F1050/15M	15	7,5	M	F1050/40H	40	20	H
F1050/19M	19	9,5	M	F1050/45M	45	22,5	M
F1050/19H	19	9,5	H	F1050/45H	45	22,5	H
F1050/20M	20	10	M	F1050/50M	50	25	M
F1050/20H	20	10	H	F1050/50H	50	25	H
F1050/22M	22	11	M	F1050/55M	55	27,5	M
F1050/22H	22	11	H	F1050/55H	55	27,5	H
F1050/25M	25	12,5	M	F1050/60M	60	30	M
F1050/25H	25	12,5	H	F1050/60H	60	30	H
F1050/30M	30	15	M	F1050/70M	70	35	M
F1050/30H	30	15	H	F1050/70H	70	35	H
F1050/35M	35	17,5	M	F1050/90M	90	45	M
F1050/35H	35	17,5	H				

## F1045

### GUIDA PER PROFILO CON INSERIMENTO CORDONETTO

*Per macchine piane*  
*For flat bed machines*

Lavoro Finito (finished work)




**PIEDINO CONSIGLIATO**  
*SUGGESTED FOOT*



**G36069HL** - per tutte le misure  
*(for all sizes)*

CORD EDGE PIPING ATTACHMENT



Codice	Entrata (A) (tape size) (mm) (inch)	Lav. finito (B) (finished size) (mm) (inch)	Spessore (S) (thickness)
F1045/19M	19 3/4	9,5 3/8	M
F1045/22M	22 7/8	11 7/16	M
F1045/25M	25 1	12,5 1/2	M
F1045/30M	30 1-3/16	15 19/32	M
F1045/35M	35 1-3/8	17,5 11/16	M

**NOTA: USARE CORDINI Ø 2 - 2,5 mm**  
*NOTE: USE CORD Ø 2 - 2,5 mm*