

**KI. DVK 1702-3, DWK 1802-3-4, V 7002-3
V 7102-3, W 8002-3, W 8102-3, WX 8702-3,
WX 8802-3, RX 9702-3, 9802-3**


Piedini 2 aghi per cuciture normali (D)
Presser feet (2 needles) for plain seaming operations (D)

KI. DVK1702D, DVK1702P, V7002D, V7102D, WX8702D, RX9702D
(per cuciture senza filo di copertura superiore - *without top cover thread*)




Piedino 2 aghi
Presser foot (2 needles)
cod. **17-6760-1** (=17-7240-1) (1/8")
cod. **17-6770-1** (=17-7340-1) (5/32")
cod. **17-6780-1** (=17-7440-1) (3/16")
cod. **17-6790-1** (=17-7540-1) (7/32")
cod. **17-6800-1** (=17-7640-1) (1/4")

KI. DWK1802D, W8002D, W8102D, WX8802D, RX9802D
(per cuciture con filo di copertura superiore - *with top cover thread*)



Piedino 2 aghi
Presser foot (2 needles)
cod. **17-8060-1** (=17-8240-1) (1/8")
cod. **17-8070-1** (=17-8340-1) (5/32")
cod. **17-8080-1** (=17-8440-1) (3/16")
cod. **17-8090-1** (=17-8540-1) (7/32")
cod. **17-8100-1** (=17-8640-1) (1/4")

KI. DWK1702B, B2000, DWK1702BK, B2000C



Piedino 2 aghi
Presser foot (2 needles)
cod. **17-7620-1** (=17-7600-1) (1/4")


Piedini 3 aghi per cuciture normali (D)
Presser feet (3 needles) for plain seaming operations (D)

KI. DVK1703D, V7003D, V7103D, WX8703D, RX9703D
(per cuciture senza filo di copertura superiore - *without top cover thread*)




Piedino 3 aghi
Presser foot (3 needles)
cod. **17-6810-1** (=17-7840-1) (7/32")
cod. **17-6820-1** (=17-7940-1) (1/4")

KI. DWK1803D, W8003D, W8103D, WX8803D, RX9803D
(per cuciture con filo di copertura superiore - *with top cover thread*)



Piedino 3 aghi
Presser foot (3 needles)
cod. **17-8170-1** (3/16")
cod. **17-8180-1** (=17-8840-1) (7/32")
cod. **17-8190-1** (=17-8940-1) (1/4")





Piedino 4 aghi
Presser foot (4 needles)
cod. **17-8930-1** (15/64")

**KI. DVK 1702-3, DWK 1802-3, V 7002-3
V 7102-3, W 8002-3, W 8102-3,
WX 8702-3, WX 8802-3**

Piedini 2 aghi passanastro (DE)
Presser feet (2 needles) for attaching elastic lace (DE)

KI. DVK1702DE, DVK1702E,
V7002DE, V7102DE, WX8702DE

KI. DWK1802DE, W8002DE,
W8102DE, WX8802DE



Piedino 2 aghi passanastro
Presser foot (2 needles) with tape guide

cod. **17-7250-1** (1/8")
cod. **17-7350-1** (5/32")
cod. **17-7450-1** (3/16")
cod. **17-7550-1** (7/32")
cod. **17-7650-1** (1/4")



Piedino 2 aghi passanastro
Presser foot (2 needles) with tape guide

cod. **17-8250-1** (1/8")
cod. **17-8350-1** (5/32")
cod. **17-8450-1** (3/16")
cod. **17-8550-1** (7/32")
cod. **17-8650-1** (1/4")

Piedini 3 aghi passanastro (DE)
Presser feet (3 needles) for attaching elastic lace (DE)

KI. DVK1703DE, DVK1703E,
V7003DE, V7103DE, WX8703DE

KI. DWK1803DE, W8003DE,
W8103DE, WX8803DE



Piedino 3 aghi passanastro
Presser foot (3 needles) with tape guide

cod. **17-7850-1** (7/32")
cod. **17-7950-1** (1/4")


Piedino 3 aghi passanastro
Presser foot (3 needles) with tape guide

cod. **17-8850-1** (7/32")
cod. **17-8950-1** (1/4")

Piedini 2 aghi per bordare (F)
Presser feet (2 needles) for binding operations (F)

KI. DVK1702F

KI. DVK1802F, V7002F, V7102F, W8002F,
W8102F, W8702F, WX8802F



Piedino 2 aghi
Presser foot (2 needles)
cod. **17-7260-1** (1/8")
cod. **17-7360-1** (5/32")
cod. **17-7460-1** (3/16")
cod. **17-7560-1** (7/32")
cod. **17-7660-1** (1/4")


Piedino 2 aghi
Presser foot (2 needles)
cod. **17-1860-1** (= 17-8260-1) (1/8")
cod. **17-1870-1** (= 17-8360-1) (5/32")
cod. **17-1880-1** (= 17-8460-1) (3/16")
cod. **17-1890-1** (= 17-8560-1) (7/32")
cod. **17-1900-1** (= 17-8660-1) (1/4")

Piedini 3 aghi per bordare (F)

Presser feet (3 needles) for binding operations (F)

KI. DVK1703F

KI. DVK1803F, V7003F, V7103F,
W8003F, W8103F, W8703F, WX8803F



Piedino 3 aghi
Presser foot (3 needles)
cod. **17-7860-1** (7/32")
cod. **17-7960-1** (1/4")

Piedino 3 aghi
Presser foot (3 needles)
cod. **17-1910-1**
cod. **17-1920-1** (= 17-8860-1) (7/32")
cod. **17-1930-1** (= 17-8960-1) (1/4")