









Serie : DDL-555; 5550; 5550N; DLN-415; 5410; ecc. LBH-781; 782, 783; 784; ecc.

## CROCHET-CAPSULE - COMPONENTI

CROCHET	CLASSE	CESTELLO	ROCCHETTO	CAPSULA	MOLLA FRIZIONE	MOLLA TENSIONE	VITE FISSAGGIO	VITE REGISTRO	MOLLA SLITTA	SLITTA		PERNO
										VITE SLITTA	PERNO	
 <b>B1830-427-OAO</b>	DDL-555 DDL-555-W DDL-555-A DDL-5550 DDL-5550-A	---	B9117-012-000 B9117-552-A00 Alluminio	B1837-012-0A0 D1837-555-BAA (Frizionale)	110-38700	040-00040394	040-00001380	040-00000591		Cerniera completa		
 <b>111-41355</b>	DDL-5550-6-WB DDL-5550-4 DDL-5550N-7 DLN-5410-4 DLN-5410-6-WB DDL-5550A-4 DDL-5550NA-7	---	B9117-012-000 B9117-552-A00 Alluminio	110-38759 Frizionale D1837-555-BAA (Frizionale)	110-38700	040-00040394	040-00001380	040-00000591	040-00002975	Cerniera completa	040-00040393	
 <b>D1830-415-BAH</b>	DDL-5550H-6-WB DDL-5550H-4	---	B9117-012-000	110-38759 Frizionale	110-38700	040-00040394	040-00001380	040-00000591	040-00002975	Cerniera completa	040-00040393	
 <b>B1830-555-HAO</b>	DDL-555H DDL-555H-4-3A	---	B9117-012-000	B1837-012-0A0 D1837-555-BAA (Frizionale)						Cerniera completa		
 <b>110-38650</b>	DDL-5550-4 (JH) DLN-5410-4 (JH)	---	B9117-012-000	110-38759 Frizionale	110-38700	040-00040394	040-00001380	040-00000591	040-00002975	Cerniera completa	040-00040393	
 <b>110-92459</b>	DDL-5550-H	---	B9117-012-000	B1837-012-0A0 D1837-555-BAA (Frizionale)						Cerniera completa		
 <b>D1830-555-BAO</b>	DDL-555-4-3B DDL-555A-4-3B	---	B9117-012-000 B9117-552-A00 Alluminio	B1837-012-0A0 D1837-555-BAA (Frizionale)						Cerniera completa		
 <b>B1808-771-0AC</b>	LBH-781 LBH-782 LBH-783 LBH-784	---	B1811-771-000	B1810-771-0BA (Frizionale) B1810-771-0A0	B1814-761-000	B1810-771-E00	B1810-761-H00	B1810-761-J00	B1810-761-F00		Slitta B1810-761-B00	Leva B1810-761-C00
											Vite slitta B1810-761-G00	Perno B1810-761-D00